


CLOVER SAFE #89

SOLDERING SAFETY



Information available from the U.S. Consumers Products Safety Commission indicates most injuries sustained while performing soldering are burns to the fingers and hands. Many of these and other soldering-related injuries were due to operator error or inattention and could have been avoided by following the soldering safety precautions given in this Clover Safe note.

Note: Lead is banned from solder products in California.

For additional information about soldering safety, go to the Clover Safe note at: <http://ucanr.org/cloversafe>.

Clover Safe Notes are prepared by the UC ANR Office of Environmental Health & Safety, in support of the Statewide 4-H Youth Development Program.

